

**TEXTRON Lycoming**

Stratford Division  
Textron Lycoming/  
Subsidiary of Textron Inc.

550 Main Street  
Stratford, CT 06497  
203/385-2000

June 25, 1991

Attn: DMR, Major  
CT Department of Environmental Protection  
Water Compliance Bureau  
122 Washington Street  
Hartford, CT 06106

RE: DMR Permit Number 0002984

Dear Sir:

Enclosed is the completed Discharge Monitoring Report (DMR) for the Textron Lycoming Stratford, Connecticut plant for the month of May 1991.

During the month of May, all six (6) of the pump houses experienced one or more emergency discharges during heavy rains that were above the permitted level for total suspended solids. In addition, the oil and grease limitations were exceeded once in each of five discharges. These discharges are the result of storm water runoff from parking areas and roadways, and the source of the contaminated water is the result of rain water flushes of these paved areas which often accumulate roadway dirt and associated oils/grease.

An in-progress engineering project has identified potential sources and is developing methods to alleviate this problem in future discharges. Among the planned activities is a complete clean-out of each pump house associated with each discharge (scheduled during our plant shut down 7/22-8/5/91). In addition, an engineering project has been developed to enlarge certain dry weather pumping systems in order to minimize the number of and frequency of wet weather storm aborts.



R.F. Kelley  
Mgr., Environmental Svcs.

RFK/fc  
BKL624