

TEXTRON Lycoming

Stratford Division
Textron Lycoming /
Subsidiary of Textron Inc.

550 Main Street
Stratford, CT 06497
203/385-2000

August 23, 1991

DMR Processing/Room 1
DEP/Water Compliance
122 Washington Street
Hartford, CT 06106

RE: DMR Permit Number CT00002984

Dear Sir:

Enclosed is the completed Discharge Monitoring Report (DMR) for the Textron Lycoming Stratford, Connecticut plant for the month of July 1991.

During the month of July, all six (6) of the pump houses experienced an emergency abort discharge during a heavy rainfall event on July 23, 1991. Five (5) of the discharges were above the limit for total suspended solids and one (1) discharge was above the limit for oil & grease.

It is believed that these values are the result of the accumulation of solids and oils in the bottom of the pump houses. In an attempt to alleviate this problem the pump houses were cleaned out during the plant shutdown the last week of July and first week of August. The clean out of the pump houses should prevent the accumulated sludge from discharging during future emergency aborts.



R.F. Kelley
Mgr., Environmental Svcs.