

TEXTRON Lycoming

Stratford Division
Textron Lycoming/
Subsidiary of Textron Inc.

550 Main Street
Stratford, CT 06497
203/385-2000

September 26, 1991

DMR Process / Room 1
DEP / Water Compliance
122 Washington Street
Hartford, CT 06106

Re: DMR Permit Number CT00002984

Dear Sir:

Enclosed is the completed Discharge Monitoring Report (DMR) for the Textron Lycoming Stratford, Connecticut Plant for the month of August 1991.

During the month of August, all six (6) of the pump houses experienced an emergency abort discharge during a heavy rainfall event. During the month, five (5) of the discharges were slightly above the maximum and/or average limit for total suspended solids and/or oil and grease.

The values for total suspended solids and oil and grease are significantly lower than was seen in previous months abort discharges. This can be attributed to the clean out of the pump houses during plant shutdown the first week of August 1991.

In an effort to further reduce the levels of oil and grease and suspended solids in the water treatment system, we have instituted a weekly sweeping program of the plant yard by Maintenance personnel to manage any accumulated dirt.



R.F. Kelley
Mgr., Environmental Svcs.

RFK/fc
BKL9262