

JR-File

TEXTRON Lycoming

Stratford Division
Textron Lycoming/
Subsidiary of Textron Inc.

550 Main Street
Stratford, CT 06497
203/385-2000

May 29, 1991

ATTN: DMR, Major
CT Department of Environmental Protection
Water Compliance Bureau
122 Washington Street
Hartford, CT 06106

RE: DMR Permit Number 0002984

Dear Sir:

Enclosed is the completed discharge monitoring report (DMR) for the Textron Lycoming Stratford, Connecticut plant for the month of April 1991.

During the month of April, two (2) of the pump houses experienced emergency discharges during heavy rains that were above the permitted level for total suspended solids. These discharges are the result of storm water runoff from parking areas and roadways, and the source of the contaminated water is the result of rainwater flushes of these paved areas which often accumulate roadway dirt. These accumulations appear to be settling in each of the stormwater basins during "dry weather" flow conditions and then stirred up through the activation of our large stormwater abort pumps. We have initiated an engineering project to examine methods to eliminate this problem in future discharges.



R.F. Kelley
Mgr., Environmental Svcs.

RFK/fc

BKL5-23