

TEXTRON Lycoming

Stratford Division
Textron Lycoming /
Subsidiary of Textron Inc.

550 Main Street
Stratford, CT 06497
203/385-2000

November 30, 1990

State of Ct. D.E.P.
Water Compliance Bureau
165 Capitol Ave.
Hartford, Ct. 06106

Attention: Mr. Mark Otfinowski

Subject: Discharge Monitoring Report, Month of October 1990,
Permit No. 0002984, Ct. File: DEP/WPC-138-023

Dear Mr. Otfinowski:

Please find enclosed the Discharge Monitoring Report for Textron Lycoming's Stratford facility for the month of October, 1990.

During heavy rains on October 24, 1990, four of the six storm water outfalls experienced discharges which exceeded the permitted limits on total suspended solids and/or oil/grease. Since these discharges are the result of storm water runoff from parking areas and roadways, the source of the contaminated water is the result of rainwater flushes of these paved areas which often contain slight losses of oil/grease from automobiles and trucks as well as accumulation of roadway dirt.

In addition to the above, pH and Phenol analysis were not performed on the same four samples because of the difficulty in preserving the samples prior to analytical testing. We are examining methods to insure these tests are performed on future samples.

And finally, it has been brought to my attention that we are currently reporting a single value for the pH of the composite samples for discharges 007 and 008 rather than a range (minimum and maximum) during the collection of the composite. Until such time we can have the appropriate monitoring/recording equipment installed, we will necessarily have to continue this practice.

Very truly yours,

Textron Lycoming



R. J. Dennis

Director, Manufacturing Services